

# AQ-300 Series USB user's Guide

## 1. System Requirements

- CPU IBM, Pentium or compatible PC
- Memory 16 M Byte
- System Microsoft® Windows® 98/ME/2000
- Graphic Adaptor VGA


## 2. USB Driver Installation

- Copy entire <USB Driver> folder from CD to hard disk.
- Connect AQ-300 USB connector to computer. Computer will detect the new device, then starts the installation program, please direct the driver to the <USB Driver> folder for driver.



Direct the path to USB Driver folder and find the driver for your system.


- c. After the installation is complete, go to **<Device Manager>** and select **<Ports (COM & LPT) >** to verify if a virtual COM port **<USB to Serial Port>** was created.



### 3. After Installation

Verify the COM port # to start using your own navigating software.


- a. Click **<Start>** menu, select **<Settings>**, then enter **<Control Panel>**.



b. After entering <Control Panel>, select <System>.



c. Select <Device Manager>, find the <Universal Serial Bus Controller> and check the Virtual COM Port, which was created by the USB driver, i.e. **USB to Serial Port (COM #)**. Please note that the Virtual COM Port number might be different from every computer.



**Note!!** Before using *navigation software*, please confirm the COM Port numbers created by your computer and provided by your navigation software. Otherwise, the navigating software won't receive the satellite signal, because of the un-match COM Port setting.

#### APPENDIX A: Introduction of the files on disk

1. **W98\_ME**: Driver for Windows 98/ME.
2. **W2K**: Driver for Windows 2000.
3. **DRemover98\_2K.exe**: un-installation program for USB driver.